Release Note for Vigor2762 Series

Firmware Version:	3.9.9.1
Release Type:	Normal - Upgrade recommended when convenient
Applied Models:	Vigor2762, Vigor2762n, Vigor2762ac, Vigor2762Vac

Vigor2762 series, the high speed router, are perfectly complied with VDSL2 environment including Vigor2762n and Vigor2762ac for speed-wanted customers. With high throughput performance and secured broadband connectivity provided by Vigor2762 series, you can simultaneously engage these bandwidth-intensive applications, such as high-definition video streaming, online gaming, and Internet telephony / access.

New Features

- None.

Improvement

- Improved: Improve the web GUI security.

- Corrected: Issues related to closing the APPE signature for network security.

- Corrected: An issue with failure to connect to Internet via SNMP server on Nagios.

- Corrected: An issue that URL Filter failure to block HTTPS websites when TLS 1.3 hybridized Kyber was enabled in the browser.

Known Issue

- None.

File and Modem Code

Note: For DSL models, there will be two folders: STD and MDM. The files in MDM folder named folder include different modem codes. If you're using a VDSL line, MDM firmware may brings out better performance.

Available modem codes for Annex A/Annex B are displayed as follows:

- "Vigor2762_v3.9.9.1_STD.zip" provides Annex A modem code 776d07_772801 & 774307_771801, and Annex B modem code 773306_771502 & 773307_771C02.
- "Vigor2762_v3.9.9.1_MDM1.zip" provides Annex A modem code 779517_773F01 & 77B507_775401, and Annex B modem code 779B06_774F02 & 779B07_774C12.

- "Vigor2762_v3.9.9.1_MDM2.zip" provides Annex A modem code 77B506_775401 & 778C06_773F01, and Annex B modem code 779906_774402 & 779B06_774C02.
- "Vigor2762_v3.9.9.1_MDM3.zip" provides Annex A modem code 77C817_775A11 & 77C717_775A11, and Annex B modem code 77C717_775A12 & 779B07_774C12.