

Release Note for Vigor2926 Series

Firmware Version:	3.9.9.9
Release Type:	Normal - Upgrade recommended when convenient
Applied Models:	Vigor2926, Vigor2926n, Vigor2926ac, Vigor2926L, Vigor2926Vac, Vigor2926Ln, Vigor2926Lac

Vigor2926 series is a broadband router which integrates IP layer QoS, NAT session/bandwidth management to help users control works well with large bandwidth. The state-of-art routing feature, VPN security, and Dual-WAN provide integrated benefits for professional users and small offices.

New Features

- None.

Improvement

- Corrected: An issue with RADIUS Request Interval not functioning properly.
- Corrected: An issue with authorization error when editing filter rule using the Firefox.
- Corrected: An issue with failure to connect to Vigor router using DrayTek Router APP.
- Corrected: Issues related to buffer overflow, unsanitized input, and uninitialized memory leaks.
- Corrected: An issue with unexpected self-reboot after configuring TR-069 ACS Server on LAN1.
- Corrected: An issue that the IP Bind List was reduced when Bind IP to MAC options were saved using the Firefox.
- Corrected: An issue with latest firmware error on APP Enforcement Profile - WCF/URL Reputation not working.

Known Issue

- None.

Notes

- Vigor router supports the mesh network; however, it is not guaranteed to fit your environment. It might not be available and restricted due to the physical connection, actual environment, signal strength, and excessive interference.

- Remove the simplified APM mechanism, and restore it to full version.

RD NO: 113_10_29